

#### LA-UR-21-23704

 $\label{lem:proved} \mbox{Approved for public release; distribution is unlimited.}$ 

Title: MCC On Boarding Section J-2 (Exhibit H) QUALITY ASSURANCE REQUIREMENTS

Author(s): Knox, Gregory Ward

Intended for: Web

Issued: 2021-04-16



#### MCC On Boarding

## Section J-2 (Exhibit H) QUALITY ASSURANCE REQUIREMENTS



**IQPA-QSS** 





#### **Quality Assurance Requirements**

#### **Subcontractor Corporate Quality Assurance Program**

- Upon MATOC Award, SUBCONTRACTOR shall submit a Quality Assurance Program for evaluation in accordance with subcontract technical and quality requirements. This may be the Subcontractors corporate QA program.
- Acceptance by Triad of the SUBCONTRACTORS Quality Assurance Program (QAP), as
  prescribed in Exhibit H, QC-01A and 01B, allows the SUBCONTRACTOR to execute this
  contract using their approved QAP.
- SUBCONTRACTORS QAP as approved by CONTRACTOR must meet the applicable requirements of **DOE Order 414.1D** (see next slide) and must address flow down of the quality requirements to lower tier subcontractors.
- Triad acceptance of SUBCONTRACTOR's QAP approval is required prior to Notice to Proceed with on-site work
- A Project Specific QA plan may on rare occasions be required for a specific task





### **Quality Assurance Requirements**

- The following DOE 414.1D Quality Criteria will apply to their work:
- Quality Program
- Personnel Training and Qualifications
- Quality Improvement
- Documents and Records
- Work Processes
- Design

- Procurement
- Inspection and Testing
- Management Assessment
- Independent Assessment
- Suspect/Counterfeit Items?



A full version of 414.1D is available at: <a href="https://www.directives.doe.gov/directives-documents/400-series/0414.1-BOrder-d">www.directives.doe.gov/directives-documents/400-series/0414.1-BOrder-d</a>
Click on the PDF document link




#### **QA Program – Table of Contents**

- 1. QA Program
  - Requirements
  - Organization
  - Subtier Suppliers and Flowdown
  - Roles & Responsibilities
- 2.0 Personnel Training and Qualification
- 3.0 Quality Improvement
  - Non-conformances
  - Corrective Action
- 4.0 Documents and Records
- 5.0 Work Processes
  - Instructions, Procedures, Drawings
  - Identification and Control of Items including Suspect/Counterfeit Items
  - Receipt Inspection
  - Material Handling and Storage

- 6.0 Design Control
  - Design Process and Procedures
  - Design Changes
  - Design Interface Control
  - Design Verification
- 7.0 Procurement
  - Processes
  - Supplier Evaluation
- 8.0 Inspection and Acceptance Testing
  - Process/Documentation
  - M&TE Calibration and Control
- 9.0 Management Assessment
- 10.0 Independent Assessment



## The Master Contract: Section Review - J: Attachments Section J-3: Quality Requirements Process



#### **The Master Contract: Section Review - J: Attachments Section J-3: Quality Requirements Process**

	SUBCONTRACT NO. 1234567 AUSES Exhibit H, Rev. 10	Task Order Exhibit H	
Purchase Request (PR) Number:  Management Level: □1 □2 □3 □4 □4IR  NQA-1? □Yes □No  Item(s) Description:	Date:	<ul> <li>Check List:         <ul> <li>Issued with each Task</li> <li>Identifies Exhibit H clause applicable to specific Task</li> </ul> </li> </ul>	
Please select the appropriate clauses:			
QC-01A Quality Assurance Program Requirements for O	ff-Site Subcontracts (Feb 2018)		
QC-01B Quality Assurance Program Requirements for O	nsite Subcontracts (Feb 2018)		
☐ QC-02 Design/Change Control for Subcontractor Provide	ed Design (May 2008)		
QC-34 Documents and Records (May 2012)			
QC-34A Documents and Records: Environment	ntal Work (May 2012)		
☐ QC-36 Software Quality Assurance (SQA) (Sep			
QC-37 Other (list applicable wording):	,		
TSME Signature:	Printed Name:	Date:	
QSME Signature:	Printed Name:	Date:	

# •QUESTIONS •& •DISCUSSION



Los Alamos National Laboratory 4/15/2021